Exceptional performance, quality, and yields



Keypoint Intelligence yield testing results for HP Color LaserJet Managed Flow MFP E87760z supplies¹



In an HP-commissioned study, all toner and drum supplies for the HP Color LaserJet Managed Flow MFP E87760z surpassed their rated yields. Testing simulated normal business use, running the devices in a stop-start pattern for eight hours a day. The results were exceptional—high-quality prints from start to finish, without a single part failure or service call during the entire 300,000-page test run.¹

Outstanding performance

The Original HP LaserJet Black Toner Cartridge for the HP Color LaserJet Managed Flow MFP E87760z surpassed its rated life by 10.9% on average. The Original HP LaserJet Cyan, Magenta, and Yellow (CMY) Toner Cartridges exceeded their rated lives by 10% on average.

The CMY drums exceeded their rated lives, delivering an extra 60,000 pages. The Black and CMY drums also produced consistent results, with no decline in image quality during the 300,000-page testing period.

Less downtime and interventions

The drums are user-replaceable, reducing the number of service calls that would be required and maximizing uptime.

Consistent quality from start to finish

Throughout testing, text and lines were found to be clean and crisp. Searchable optical character recognition (OCR) analysis of the printed output found near-identical accuracy results from beginning to end of the test.¹

Quality of optical color density remained stable throughout the test, which means users can expect the last printed page to be as good as the first.¹

Not a single failure

No components (fuser, developer units, etc.) experienced failures or required premature replacement.¹

December 2022 Keypoint Intelligence study, commissioned by HP. Long-Life Consumable and supply yield testing for the HP Color LaserJet Managed Flow MFP E87760z. See: https://h20195.www2.hp.com/v2/GetDocument.aspx?docname=4AA8-2605ENW.

© Copyright 2023 HP Development Company, L.P. The information contained herein is subject to change without notice. The only warranties for HP products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein.